



Technical Bulletin

(1005341 Rev. A)

(Was 1000527-001)

August 12, 2003

Updated June 26, 2006

Models Affected:

Various 4000X2-HSP models

Details:

Bios can not be updated if the BMC is 1.10 or earlier

Component Part Numbers (if required)

1) 1000527 (Intel® SE7501BR2 Bryson Motherboard)

Solution:

Update BMC to 1.11 before updating Bios