



**\*Technical Bulletin\***

(1005343 Rev. A)

(Was 1001996-001)

September 29, 2003

Updated June 26, 2006

**Models Affected:**

1003027 (2000S-SF)

1003289 (2000S-SF-AS)

**Details:**

The original SUN V240 with SUN video card, Antares Audio card and Teac CDW/DVD. It was tested with Solaris 8 Build code (BC) 12/02. It was observed only Solaris 8 BC 12/02 or later has to be used on this unit. The previous versions cannot be installed using the CD-ROM drive.

**Component Part Numbers (if required)**

- 1) 1001996 (Antares PCI Cool Audio)

**Solution:**

We performed testing going on forward and tested version of Solaris 9 BC 4/03 and found there were no drivers for the current only SUN compatible available audio card. At this point there is no set date on the Solaris 9 driver availability from Antares as they are being bought by another company and they are in transition phase.